

SERVICE - INFO



**LuK Nr: 133 0270 10 – 330mm TBFR
133 0272 10 – 330mm TBFR**

Bulletin 988 2000 550

NEW HOLLAND FORD – 5000, 6000, 7000, 8000 & 9000 Series**

Info:	133 0272 10 replaces / ersetzt / remplace / sustituye a / sostituisce 133 0004 50 & 133 0005 50 133 0270 10 replaces / ersetzt / remplace / sustituye a / sostituisce 133 0020 11 & 133 0032 50 & 133 0245 10
GB	When replacing a 4 lever coil spring clutch with LuK diaphragm type clutch, shims are not required.
D	Wenn die 4-Hebel-Schraubenfederkupplung durch eine LuK-Tellerfederkupplung ersetzt wird, entfallen die Segmentbleche.
F	Le remplacement d'un embrayage à ressorts hélicoïdaux à 4 leviers par un embrayage à diaphragme LuK ne requiert pas de cales de réglage.
E	Al reemplazar el embrague de muelles helicoidales con 4 patillas por el de diafragma no es necesario colocar calzos.
I	Quando si sostituisce una frizione a molle elicoidali a 4 leve con una frizione di tipo a diaframma LuK, non sono necessari distanziatori.
LuK Repsets:	633 1126 19 = 133 0272 10 + 333 0032 10 633 1130 17 = 133 0272 10 + 333 0032 10 + 500 0199 40 + 410 0021 00 633 1127 09 = 133 0272 10 + 333 0033 06 633 1131 07 = 133 0272 10 + 333 0033 06 + 500 0199 40 + 410 0021 00

****** For model information please see LuK Catalogue / Die genaue Fahrzeugzuordnung entnehmen Sie bitte dem LuK-Katalog / Pour les informations le modèle veuillez consulter le catalogue LuK / Para obtener información sobre el modelo, rogamos consulte el catálogo de LuK / Per informazioni sul modello consultare il catalogo LuK

SERVICE - INFO



133 0020 11



133 0032 50



133 0245 10



133 0270 10



133 0004 50



133 0005 50



133 0272 10



Issue Level 4