

SERVICE - INFO



LuK Nr: 131 0290 10 – 310mm TBFR

Bulletin 988 2000 590

NEW HOLLAND FORD – 5000, 6000 & 7000 Series**

Info:	131 0290 10 replaces / ersetzt / remplace / sustituye a / sostituisce 131 0035 50
(GB)	When replacing a 4 lever coil spring clutch with LuK diaphragm type clutch, shims are not required.
(D)	Wenn die 4-Hebel-Schraubenfederkupplung durch eine LuK-Tellerfederkupplung ersetzt wird, entfallen die Segmentbleche.
(F)	Le remplacement d'un embrayage à ressorts hélicoïdaux à 4 leviers par un embrayage à diaphragme LuK ne requiert pas de cales de réglage.
(E)	Al reemplazar el embrague de muelles helicoidales con 4 patillas por el de diafragma, no es necesario colocar calzos.
(I)	La sostituzione di una frizione a molle elicoidali a 4 lamelle con una frizione a diaframma LuK non richiede spessori.
LuK Repsets:	631 1073 09 = 131 0290 10 + 331 0152 10 631 1073 07 = 131 0290 10 + 331 0152 10 + 500 0199 40 + 410 0021 00 631 1074 09 = 131 0290 10 + 330 0117 10 631 1074 07 = 131 0290 10 + 330 0117 10 + 500 0199 40 + 410 0021 00

** For model information please see LuK Catalogue / Die genaue Fahrzeugzuordnung entnehmen Sie bitte dem LuK-Katalog / Pour les informations le modèle veuillez consulter le catalogue LuK / Para obtener información sobre el modelo, rogamos consulte el catálogo de LuK / Per informazioni sul modello consultare il catalogo LuK

131 0035 50



131 0290 10



Issue Level 3