

SERVICE - INFO



LuK Nr: 630 2461 09 – 280/295mm TGU6 **Bulletin 988 2000 990**

STEYR – M975, M986, 955, 964, 970E, 975 & 8070

Info:	630 2461 09 Replaces / ersetzt / remplace / sustituye a / sostituisce 230 0030 20 630 2461 09 Replaces / ersetzt / remplace / sustituye a / sostituisce 330 0088 20
LuK Repset:	630 2461 09 = 230 0028 10 + 329 0006 10 + 12 x M8 x 1.25 x 95mm bolts. 630 2462 09 = 230 0028 10 + 329 0007 10 + 12 x M8 x 1.25 x 95mm bolts.

****** For model information please see LuK Catalogue / Die genaue Fahrzeugzuordnung entnehmen Sie bitte dem LuK-Katalog / Pour les informations le modèle veuillez consulter le catalogue LuK / Para obtener información sobre el modelo, rogamos consulte el catálogo de LuK / Per informazioni sul modello consultare il catalogo LuK

230 0030 20




330 0088 20




+



230 0028 10



329 0006 10



+



630 2461 09