

SERVICE - INFO



LuK Nr: 131 0038 11 – 305mm DBFR

Bulletin 988 2000 580

CASE IH – 74, 84, 85, 95, 3200 & 4200 Series

Info:	131 0038 11 replaces / ersetzt / remplace / sustituye a / sostituisce 131 0038 10
(GB)	Please ensure that the flywheel is machined to a pot depth of 35.9mm, [1.413"].
(D)	Das Schwungrad ist auf eine Tiefe von 35.9mm, [1.413"] auszdrehen, siehe unten.
(F)	Veuillez vous assurer que le volant-moteur est rectifié à une profondeur de 35.9mm, [1.413"].
(E)	Asegúrese de que el volante está mecanizado hasta una profundidad de 35.9mm, [1.413"].
(I)	Controllare che il volano venga rettificato a una profondità di 35.9mm, [1.413"].
LuK Repsets:	631 1067 19 = 131 0038 11 + 331 0154 11 631 1067 10 = 131 0038 11 + 331 0154 11 + 500 1046 50 + 410 0026 00
	131 0038 11 = 131 0038 12 + 434 0342 10

131 0038 10

1970876C1

131 0038 11

434 0342 10

