

# SERVICE - INFO



**LuK Nr: 133 0608 10 – 330mm DBFP  
133 0271 10 – 330mm TBFR**

**Bulletin 988 2000 600**

**NEW HOLLAND FORD – 3000, 4000, 5000 Series & Industrial \*\***

|              |                                                                                                                                                                                |
|--------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| <b>Info:</b> | <b>133 0608 10 replaces / ersetzt / remplace / sustituye a / sostituisce 133 0018 10<br/>133 0271 10 replaces / ersetzt / remplace / sustituye a / sostituisce 133 0017 10</b> |
| <b>(GB)</b>  | When replacing a 4 lever coil spring clutch with LuK diaphragm type clutch, shims are not required.                                                                            |
| <b>(D)</b>   | Wenn die 4-Hebel-Schraubenfederkupplung durch eine LuK-Tellerfederkupplung ersetzt wird, entfallen die Segmentbleche.                                                          |
| <b>(F)</b>   | Le remplacement d'un embrayage à ressorts hélicoïdaux à 4 leviers par un embrayage à diaphragme LuK ne requiert pas de cales de réglage.                                       |
| <b>(E)</b>   | Al reemplazar el embrague de muelles helicoidales con 4 patillas por el de diafragma no es necesario colocar calzos.                                                           |
| <b>(I)</b>   | Quando si sostituisce una frizione a molle elicoidali a 4 leve con una frizione di tipo a diaframma LuK, non sono necessari distanziatori.                                     |

**\*\*** For model information please see LuK Catalogue / Die genaue Fahrzeugzuordnung entnehmen Sie bitte dem LuK-Katalog / Pour les informations le modèle veuillez consulter le catalogue LuK / Para obtener información sobre el modelo, rogamos consulte el catálogo de LuK / Per informazioni sul modello consultare il catalogo LuK

**133 0018 10**



**133 0608 10**



**133 0017 10**



**133 0271 10**



Issue Level 3