

LuK Nr: 228 0072 10 – 280mm TGU6

Bulletin 988 2001 110

STEYR – 8055, 8060N, 8070N

Info:	228 0072 10 Replaces / ersetzt / remplace / sustituye a / sostituisce 228 0072 21
ⒼⒷ	Bolts 6 x M8 x 1.25 x 95mm are supplied to fit new LuK clutch 228 0072 10.
Ⓓ	Schrauben 6 x M8 x 1.25 x 95mm passend für die neue LuK-Kupplung 228 0072 10.
Ⓕ	Les boulons 6 x M8 x 1.25 x 95mm sont fournis pour s'adapter au nouvel embrayage LuK 228 0072 10.
Ⓔ	Los tornillos 6 x M8 x 1.25 x 95mm se distribuyen para el nuevo modelo de embrague LuK 228 0072 10.
Ⓘ	Bulloni 6 x M8 x 1.25 x 95mm in dotazione per la nuova frizione LuK 228 0072 10.
Luk Repset:	628 1358 09 = 228 0072 10 [328 0109 10] + 328 0108 10 + 6 x M8 x 1.25 x 95mm

