

LuK Nr: 231 0042 10 – 305/305mm TGU6
Bulletin 988 2002 000

DAVID BROWN – 1190, 1194, 1210, 1290, 1294, 1390, 1394, 1410, 1412, 1490 & 1494

Info:	231 0042 10 replaces / ersetzt / remplace / sustituye a / sostituisce 231 0042 40 / 231 0040 41 / 231 0041 41
GB	Bolts 3/8"UNC x 2"are supplied to fit new LuK clutch 231 0042 10.
D	Schrauben 3/8"UNC x 2" passend für die neue LuK-Kupplung 231 0042 10.
F	Les boulons 3/8"UNC x 2" sont fournis pour s'adapter au nouvel embrayage LuK 231 0042 10.
E	Los tornillos 3/8"UNC x 2" se distribuyen para el nuevo modelo de embrague LuK 231 0042 10.
I	Bulloni 3/8"UNC x 2" in dotazione per la nuova frizione LuK 231 0042 10.

231 0040 41
231 0041 41
231 0042 40

231 0042 10

